



CODE ENFORCEMENT BOARD HEARING AGENDA

FEBRUARY 23, 2016 9:00 AM

CITY COMMISSION MEETING ROOM - CITY HALL 100 N ANDREWS AVENUE FT. LAUDERDALE, FL 33301

CODE ENFORCEMENT BOARD

Code of Ordinances: Sec. 11-3.

PURPOSE: Hear and decide cases in which violations are alleged of any provision of the Florida Building Code, Broward County Amendments and violations of the Code of Ordinances of the City of Fort Lauderdale when alleged together with a violation of the Florida Building Code.

Note: If any person decides to appeal any decision made with respect to any matter considered at this public meeting or hearing he/she will need a record of the proceedings and for such purpose, he/she may need to ensure that a verbatim record of the proceedings is made, which record includes the testimony and evidence upon which the appeal is to be based.

Board Members: • Chad Thilborger, **Chair** • Paul Dooley, **Vice Chair** • Joan Hinton

- Lakhi Mohnani Patrick McGee Joshua Miron (alternate) Robert Smith (alternate)
- Michael Madfis (alternate) Board Attorney: Bruce Jolly

TWO OR MORE FORT LAUDERDALE CITY COMMISSIONERS OR MEMBERS OF A CITY OF FORT LAUDERDALE ADVISORY BOARD MAY BE IN ATTENDANCE AT THIS MEETING.

HEARING SCHEDULED

CASE NO: CE12120316

CASE ADDR: 3400 GALT OCEAN DR # 2107S

OWNER: FISCHER CORP INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH AN INTERIOR RENOVATION COMPLETED WITHOUT THE REQUIRED PERMITS

AND/OR INSPECTIONS.

FBC(2010) 110.9

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE AFTER THE FACT PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS

CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE14022168

CASE ADDR: 5100 BAYVIEW DR # 301
OWNER: BONELL, JOSEPHINE

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

INTERIOR REMODELING WORK DONE WITHOUT THE REQUIRED

PERMITS AND/OR INSPECTIONS.

CASE NO: CE14071378

CASE ADDR: 2624 NE 32 ST # 108

OWNER: JS GLOBAL INC INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS HAD A COMPLETE INTERIOR REMODEL WITHOUT ALL THE REQUIRED PERMITS FIRST BEING OBTAINED. THE ISSUED PERMITS DID NOT HAVE THE REQUIRED A.T.F. PLAN REVIEW AND WERE NOT

PROPERLY DOUBLE FEE. THE WORK WAS STARTED PRIOR TO PERMITS BEING ISSUED. THE PERMITS SHOULD HAVE BEEN

FLAGGED AS A.T.F. AND DOUBLE FEES WOULD HAVE

APPLIED.

FBC(2010) 110.9

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PAY ALL REQUIRED ATF FEES, SCHEDULE AND PASS ALL REQUIRED INSPECTIONS, AND PROPERLY CLOSE ALL THE REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15041877

CASE ADDR: 4300 N OCEAN BLVD # 17J

OWNER: HOLOTKA, JOANNE M
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH AN INTERIOR

REMODEL WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

FBC(2010) 110.9

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE AFTER THE FACT PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS

CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15101288 CASE ADDR: 2890 NE 26 PL

OWNER: WARDELL, ANDREW WHITAKER H/E

WARDELL, DIANA MUIR

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. A POOL HEATER AND ELECTRICAL DISCONNECT

INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15101589

CASE ADDR: 3200 NE 36 ST # 411

OWNER: BAUCO, DOMENICO

BAUCO, MARISA

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH A KITCHEN AND BATHROOM REMODEL WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 110.2

A PRELIMINARY INSPECTION WILL BE REQUIRED BEFORE THE AFTER THE FACT PLAN REVIEW IS APPROVED.

FBC(2014) 110.6

THE CONDO UNIT OWNER WILL BE REQUIRED TO SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH A KITCHEN AND BATHROOM REMODEL WHICH INCLUDES BUT IS NOT LIMITED TO:

1. FRAMING AND DRYWALL WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 109.3.3

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

CASE NO: CE15102328

CASE ADDR: 36 PORTSIDE DR

OWNER: LOMBARDI, THOMAS R

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS TOWNHOUSE UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE KITCHEN AND BATHROOMS BEING REMODELED WHICH INCLUDES FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS TOWNHOUSE UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE KITCHEN AND BATHROOMS BEING REMODELED WHICH INCLUDES THE PLUMBING FIXTURES BEING REMOVED AND REPLACED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS TOWNHOUSE UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE KITCHEN AND BATHROOMS BEING REMODELED WHICH INCLUDES ELECTRICAL WORK BEING PERFORMED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND OR INSPECTIONS.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15120399
CASE ADDR: 2157 NE 63 CT

OWNER: ASURION FINANCIAL INC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE KITCHEN AND BATHROOMS ARE BEING COMPLETELY DEMOLISHED AND REMODELED WHICH INCLUDES FRAMING AND DRYWALL WORK PERFORMED WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE KITCHEN AND BATHROOMS ARE BEING COMPLETELY DEMOLISHED AND REMODELED WHICH INCLUDES REMOVING AND REPLACING THE PLUMBING FIXTURES WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE KITCHEN AND BATHROOMS ARE BEING REMODELED WHICH INCLUDES REMOVING AND REPLACING ELECTRICAL DEVICES WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15120539

CASE ADDR: 3020 SEVILLE ST

OWNER: 3020 SEVILLE PROPERTIES LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. WINDOWS AND DOORS BEING REPLACED.
- 2. REMODELING OF THE INTERIOR ROOMS WHICH INCLUDE FRAMING AND DRYWALL.
- 3. REBUILDING EXTERIOR STAIRS AND DECKS.
- 4. REPLACING THE ROOF ALONG WITH NEW A/C. ROOF STANDS WITHOUT THE REQUIRED STRUCTURAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE KITCHENETTES AND BATHROOMS ARE BEING COMPLETELY REMODELED. REMOVING AND REPLACING PLUMBING FIXTURES THROUGHOUT THE BUILDING WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL WORK IS BEING DONE THROUGHOUT THE BUILDING WHICH INCLUDES NEW WIRING, NEW LOW VOLTAGE WIRING, NEW ELECTRICAL BOXES, NEW ELECTRICAL DISCONNECTS AND ELECTRICAL DEVICES BEING REMOVED AND REPLACED WITHOUT THE REQUIRED ELECTRICAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL WORK IS BEING PERFORMED WHICH INCLUDES INSTALLING NEW MINI SPLIT A/C SYSTEMS FOR THE ROOMS AND NEW UNITS PLACED ON THE GROUND AND ROOF WITHOUT THE REQUIRED MECHANICAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THESE HOTEL UNITS AND THE HOTEL BUILDING, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

FBC (2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15120540 CASE ADDR: 3024 SEVILLE ST

OWNER: 3020 SEVILLE PROPERTIES LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. WINDOWS AND DOORS BEING REPLACED.
- 2. REMODELING OF THE INTERIOR ROOMS WHICH INCLUDE FRAMING AND DRYWALL, REBUILDING EXTERIOR STAIRS AND DECKS, AND REPLACING THE ROOF ALONG WITH NEW A/C. ROOF STANDS WITHOUT THE REQUIRED STRUCTURAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL WORK BEING PERFORMED WHICH INCLUDES INSTALLING NEW MINI SPLIT A/C SYSTEMS FOR THE ROOMS AND NEW UNITS PLACED ON THE GROUND AND ROOF WITHOUT THE REQUIRED MECHANICAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE KITCHENETTES AND BATHROOMS ARE BEING COMPLETELY REMODELED AND REMOVING AND REPLACING PLUMBING FIXTURES THROUGHOUT THE BUILDING WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL WORK BEING DONE THROUGHOUT THE BUILDING WHICH INCLUDES NEW WIRING, NEW LOW VOLTAGE WIRING, NEW ELECTRICAL BOXES, NEW ELECTRICAL DISCONNECTS AND ELECTRICAL DEVICES BEING REMOVED AND REPLACED WITHOUT THE REQUIRED ELECTRICAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THESE HOTEL UNITS AND THE HOTEL BUILDING, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

FBC (2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16010199
CASE ADDR: 2811 NE 56 CT
OWNER: LACHO & FRANZ LLC
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. ALTERING THE SEAWALL CAP.
- 2. ALTERING EXTERIOR OPENINGS ON THE HOUSE.
- 3. PATIO ENCLOSURE.
- 4. INTERIOR RENOVATIONS WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. REMOVING AND REPLACING PLUMBING FIXTURES WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. REMOVING AND REPLACING ELECTRICAL WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. REMOVING AND REPLACING THE MECHANICAL SYSTEM WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY, SEVERITY, LIFE SAFETY, AND POTENTIAL LIABILITY OF THE VIOLATIONS FOR THIS PROPERTY, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED AND BROUGHT INTO COMPLIANCE PER FLORIDA BUILDING CODE.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16011026
CASE ADDR: 1009 NE 17 CT
OWNER: CONROY, KYLE
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS. THIS PROPERTY WAS ORIGINALLY PERMITTED AS A TWO FAMILY DWELLING AND WAS ILLEGALLY CONVERTED IN A TRIPLEX UNIT WITHOUT THE PROPERTY CERTIFICATE OF OCCUPANCY. THERE HAS BEEN EXTENSIVE REMODELING WORK DONE ON THIS BUILDING WHICH INCLUDES BUT IS NOT LIMITED TO WINDOWS AND DOORS REPLACED, KITCHEN AND BATHROOM REMODELED, LAYOUT OF THE BUILDING HAS BEEN ALTERED.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. PLUMBING ALTERATION MADE:
 - A. REMODELING KITCHENS, BATHROOMS, REMOVING AND REPLACING PLUMBING FIXTURES WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. ELECTRICAL ALTERATIONS MADE:
 - A. ELECTRICAL PANELS REPLACED, DISCONNECTS INSTALLED, ELECTRICAL OUTLETS, SWITCHES, DEVICES REMOVED, REPLACED OR RELOCATED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITH REMOVING AND REPLACING THE A/C UNITS WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY, PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

CASE NO: CE14090643

CASE ADDR: 6311 BAY CLUB DR # 6311-3 OWNER: PIERCE, JOSEPH & JANET

INSPECTOR: ALEJANDRO DELRIO

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:
1. KITCHEN REMODELING.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15061766
CASE ADDR: 1004 SW 7 ST
OWNER: SCHATZ, DAVID W
INSPECTOR: ALEJANDRO DELRIO

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. PAVERS INSTALLATION ON DRIVEWAY.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15081007

CASE ADDR: 750 ALABAMA AVE

OWNER: HERMES PROPERTY DEVELOPMENT LLC %TE

INSPECTOR: ALEJANDRO DELRIO

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. KITCHEN AND BATHROOM RENOVATION.

- 2. ADDITION OF A SECOND BATHROOM IN UTILITY ROOM AREA.
- 3. REPLACEMENT OF FRONT DOOR AND WINDOWS.
- 4. ALTERATION OF ELECTRICAL SYSTEM IN UTILITY ROOM.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT, THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15070098 CASE ADDR: 5200 NW 31 AVE

VILLAS AT LAKEVIEW CONDO ASSN IN OWNER:

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. BUILT STORAGE SHEDS ON PROPERTY WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2014) 105.3.1.4.18

INSTALLED WOOD FENCE WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2014) 105.3.1.4.4

INSTALLED WATER SUPPLY LINES/SPRINKLER/SEWER LINES WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15070837
CASE ADDR: 1631 NW 26 TER
OWNER: MOORE, CARLTON EST

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2014) 1029.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. DOORS HAVE BEEN BLOCKED BY THE INSTALLATION OF DEVICE(S) REQUIRING A KEY/TOOL TO OPERATE.

FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. HOME ALTERED AND CONVERTED TO ROOMING HOUSE WITHOUT PERMIT.
- 2. KITCHEN HAS BEEN REMODELED.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS. INSTALLATION AND MODIFICATION BUT NOT LIMITED TO:

1. KITCHEN HAS BEEN REMODELED AND THE PLUMBING SYSTEM HAS BEEN ALTERED AND/MODIFIED, BUT NOT LIMITED TO THE REMOVAL AND INSTALLATION OF FIXTURES.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A SINGLE FAMILY HOME TO A ROOMING HOUSE WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE15081360
CASE ADDR: 621 SE 5 CT
OWNER: BLUEWATER INC
INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. DRIVEWAY PAVERS INSTALLED WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.18

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. FENCE INSTALLED WITHOUT A PERMIT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15082061

CASE ADDR: 86 ISLE OF VENICE
OWNER: SANTIAGO'S HOUSE LLC

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED NEW WOOD DECK WITHOUT OBTAINING THE REQUIRED PERMTS.

FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED WINDOWS AND DOORS WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED NEW TOILET FIXTURE WITHOUT OBTAINING THE REQUIRED PERMIT. IT IS NOW BACKED UP AND UNSANITARY.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

._____

CASE NO: CE15100767
CASE ADDR: 1029 NW 1 AV
OWNER: ANGELS TJ LLC
INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. STRUCTURE WAS BUILT AT THE FRONT ENTRY.

FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. NO PERMIT FOR CONDENSOR UNIT REPLACEMENT.

FBC (2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE HEREBY RESERVE THE AUTHORITY TO SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15121199

CASE ADDR: 1251 E SUNRISE BLVD
OWNER: ROSHNI INVESTMENTS INC

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2014) 1013.4

1. OPENING ON GUARDRAILS EXCEED THE MAXIMUM ALLOWABLE UNDER THE SECTIONS OF THIS CODE OF 4 INCHES.

2. THIS IS AN EXIGENT LIFE AND SAFETY HAZARD THAT IMMEDIATE ATTENTION IS REQUIRED TO MAKE SAFE.

FBC(2014) 110.6

THIS VIOLATION IS IN PROGRESS AND REQUIRES INSPECTIONS AND APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE MITIGATION AND PERMITTING PROCESS.

CASE NO: CE09120460
CASE ADDR: 2240 NW 30 TER
OWNER: BANK OF AMERICA NA

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. INTERIOR REMODELING WORK. NEW DRYWALL ON CEILING AND WALLS
- 2. REROOF BETWEEN 2005 AND 2006.
- 3. NEW CABINETS AND FIXTURES IN THE KITCHEN AND BATHROOM AREAS.
- 4. NEW ENTRANCE DOORS WITH REDESIGNED OPENINGS.
- 5. ALL THE WINDOWS WERE REPLACED.
- 6. THE PROPERTY WAS BOARDED-UP WITHOUT A CERTIFICATE. (COMPLIED 4/10)

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. THE KITCHEN AND BATHROOM FIXTURES WERE REPLACED.
- 2. THERE ARE NEW SHOWER AND TUB THAT WERE REPLACED.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ELECTRICAL LOAD DEMAND WAS INCREASED BY ADDING A CENTRAL A/C WITH ELECTRICAL HEATERS AND ADDITIONAL LIGHTS, WALL OUTLETS THAT HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED AMPERAGE LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. A CENTRAL A/C SYSTEM WAS INSTALLED WITH DUCT WORK AND ELECTRICAL HEATER. VENTILATION SYSTEM FOR KITCHEN AND BATHROOMS.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS THROUGH THE PERMITTING AND INSPECTION PROCESS.

FBC(2007) 1612.1.2

ALL THE WINDOWS AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS

FBC(2007) 1626.1

THE NEW WINDOWS AND DOOR WITH GLASS NEED TO BE IMPACT RESISTANT OR BE PROTECTED BY AN APPROVED HURRICANE PROTECTION SYSTEM.

RETURN HEARING (OLD BUSINESS)

CASE NO: CE13051997 CASE ADDR: 1515 NW 7 AVE

OWNER: FEDERAL NATIONAL MORTGAGE ASSN

NEW OWNERS: YUTHASUNTHORN, CHANCE

YUTHASUNTHORN, SIRILUK

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THE SINGLE FAMILY DWELLING HAS BEEN ALTERED IN THE

FOLLOWING MANNER WITHOUT A PERMIT:
1. NEW WINDOWS HAVE BEEN INSTALLED.

2. A KITCHEN REMODELING PROJECT IS IN PROGRESS.

3. A BATHROOM REMODELING PROJECT IS IN PROGRESS.

FBC(2010) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED BY THE KITCHEN AND BATHROOM REMODELING WITHOUT A PERMIT.

FBC(2010) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED WITH THE KITCHEN AND BATHROOM REMODELING WITHOUT A PERMIT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE13061394 CASE ADDR: 6837 NW 29 AV

OWNER: US BANK NATIONAL ASSN TRSTEE

% AMERICAS SERVICING COMPANY

NEW OWNER: JAZSAM HOMES LLC

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

1. THE OWNER ADDED A 2ND FLOOR BATHROOM ILLEGALLY.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT OBTAINING THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

._____

CASE NO: CE14011733 CASE ADDR: 3114 NE 23 CT

OWNER: FUSSELL, GEORGE JR

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. CONSTRUCTED BOAT LIFT WITHOUT PERMIT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITING PROCESS.

CASE NO: CE14031507 CASE ADDR: 416 SW 11 CT

OWNER: REYNOLDS, STUART L

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

- 1. THE PROPERTY OWNER HAS CONVERTED THIS SINGLE FAMILY HOUSE INTO A DUPLEX RENTING OUT THE BACK AND FRONT TO TWO DIFFERENT FAMILIES. THEY HAVE ENCLOSED THE CARPORT AND HALLWAY LEADING TO ONE PART OF THE HOUSE TO CREATE THE NEW FLOOR PLAN.
- 2. THEY HAVE ADDED ELECTRIC OUTLETS AND PLUMBING FIXTURES IN THE ENCLOSED CARPORT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THE CARPORT HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION CLASS U (UTILITY) TO R-3 (LIVING SPACE) WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE14032107 CASE ADDR: 2006 NE 29 CT

OWNER: MARTIN, A LEE JR & LISA A INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. INSTALLED WINDOWS WITHOUT A PERMIT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE14050728 CASE ADDR: 2840 NE 25 ST

CLEMENTE, DANIELA VALENTI OWNER:

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. BUILT DOCK.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE14081054

CASE ADDR: 1834 LAUD MANORS DR OWNER: WSC BRICKELL LLC

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS AS FOLLOWS:

- 1. WINDOWS AND EXTERIOR DOORS WERE REPLACED.
- 2. THE DWELLING WAS RE-ROOFED.
- 3. THE EXISTING CARPORT THAT WAS BUILT WITH THE DWELLING WAS ENCLOSED INTO A LIVING SPACE.
- 4. A DUCTED CENTRAL A/C WAS INSTALLED.
- 5. INTERIOR RENOVATIONS AND ELECTRICAL AND PLUMBING UPGRADES WERE PERFORMED INSIDE THE KITCHEN AND BATHROOMS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14092255
CASE ADDR: 1231 NW 46 CT
OWNER: LANE, KENNETH R

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS, AS FOLLOWS:

1. THE DWELLINGS CARPORT HAS BEEN ENCLOSED INTO A

LIVING SPACE.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

....

CASE NO: CE14111191

CASE ADDR: 5955 NW 31 AVE # A OWNER: LAKEVIEW PLAZA INC

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. INTERIOR RENOVATION OF WALL PARTITIONS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITING PROCESS.

CASE NO: CE14111588 CASE ADDR: 814 SW 26 CT

OWNER: RANDOLPH, DONNA LE

BURNS IRREVOCABLE FAM TR

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS.

REFERRED TO PROPERTY BY FORT LAUDERDALE POLICE. THERE ARE UNSAFE CONDITIONS INSIDE THE DWELLING.

- 1. THE ELECTRICAL PANEL WAS REMOVED FROM THE SUPPORTING WALL AND IS HANGING BY THE WIRES.
- 2. THE ELECTRICAL METER CAN HAS BEEN JUMPED WITH WIRES TO SUPPLY POWER TO THE DWELLING.
- 3. DRYWALL IS BEING REPLACED.
- 4. PLUMBING WORK IN PROGRESS INSIDE THE BATHROOMS.
- 5. A SHED THAT WAS INSTALLED WITHOUT A PERMIT. IT IS IN DISREPAIR. IT MUST BE REPAIRED OR REMOVED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC(2010) 1604.1

THE STRUCTURES FOR THE ROOF AND WALLS BELONGING TO THE REAR STORAGE SHED; DOES NOT MEET THE STANDARD FOR GRAVITY LOADING AND HAS NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS; ALL THE STRUCTURES THAT WERE DONE ILLEGALLY ARE DEEM TO BE UNSAFE AS PER FBC 116.1.2 AND THE CONSTRUCTION IS UNDER DESIGNED, AND IT WOULD NOT PROVIDE THE REQUIRED RESISTANCE TO THE WIND'S UPLIFT.

CASE NO: CE14120163 CASE ADDR: 5920 NE 21 RD OWNER: SOUA, MOUEZ H/E

SOUA, MAHER

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. ENCLOSED CARPORT AND CONVERTED TO GARAGE.
 2. REPLACED WINDOWS AND DOORS FRONT ELEVATION.
- 3. INSTALLED GARAGE DOOR.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15011130

CASE ADDR: 951 ALABAMA AVE

TROPNEVAD PROMOTIONS LLC

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. ATTACHED ADDITIONS AND INTERIOR RENOVATIONS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITING PROCESS.

CASE NO: CE15031679 CASE ADDR: 1501 NW 19 AVE OWNER: GRANT FLA LLC INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

- 1. FLORIDA ROOM WAS CONVERTED INTO A THIRD BEDROOM WITH A BATHROOM. THERE ARE 15 PEOPLE LIVING IN THE DWELLING AS PER CODE OFFICER QUINTERO.
- 2. THERE ARE NEW WINDOWS AND DOORS INSTALLED OR REPLACED ON THE PROPERTY.
- 3. A CENTRAL A/C SYSTEM UNIT INSTALLED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15040159 CASE ADDR: 1312 NW 9 AV

OWNER: COMMUNITY 8 PROPERTIES LLC

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS, INSPECTIONS AND CO:

1. 2 ELECTRIC METERS AND 2 MAIL BOXES FOR 4 UNITS. THIS CASE IS ABOUT CHANGING THE USE OF A DUPLEX INTO A FOUR RENTAL UNIT. THIS HAPPENED BEFORE UNDER CASE CE14070224 FOR THE SAME VIOLATION.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC(2010) 111.1.1

F.B.C. (2010) 111.1.1 Certificate of Occupancy. THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A DUPLEX TO A FOUR RENTAL APARTMENT WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE15050398 CASE ADDR: 1216 NE 16 AVE

OWNER: BENNETT, RONALD D & JILLIAN S

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. THE BUILDING HAS BEEN ALTERED FROM A DUPLEX TO TRIPLEX WITHOUT A PERMIT. ALTERATIONS ARE NOT LIMITED TO STRUCTURAL, PLUMBING, ELECTRICAL AND MECHANICAL.

FBC(2010) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ALTERATIONS OF PLUMBING SYSTEM TO ACCOMMODATE THE ILLEGAL USE AS A TRIPLEX WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2010) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. THE ELECTRICAL SYSTEM HAS BEEN ALTERED TO ACCOMMODATE ILLEGAL USE AS A TRIPLEX WITHOUT A PERMIT.

FBC(2010) 105.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. THE MECHANICAL SYSTEM HAS BEEN ALTERED TO ACCOMMODATE ILLEGAL USE AS A TRIPLEX WITHOUT A PERMIT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A DUPLEX TO A TRIPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE15061690
CASE ADDR: 3341 NE 42 CT
OWNER: BIELEN, ARVIN N

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BUILDING STRUCTURES IN BACKYARD AND/OR BACK OF PROPERTY WITHOUT OBTAINING BUILDING PERMITS AS REQUIRED BY THE FLORIDA BUILDING CODE.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15072462
CASE ADDR: 1119 NE 15 AVE
OWNER: 1119 PROGRESSO LLC

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. KITCHEN/BATH REMODEL WITHOUT PERMIT.
- 2. CONVERTED GARAGE INTO A BEDROOM AND/OR LIVING SPACE WITHOUT PERMIT.
- 3. REMOVED AND REPLACED FIXTURES.
- 4. ATF PERMITS THAT WERE APPLIED FOR WERE VOIDED AND/OR NOT ISSUED.

FBC(2014) 105.3.1.4.11

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF THE MECHANICAL COMPONENTS AND/OR MODIFYING THE MECHANICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING CONDENSER UNITS, EVAPORATOR UNITS, DUCT WORK, ELECTRICAL COMPONENTS, THERMOSTATS, COOLING TOWERS, HEATERS, AND OTHER MECHANICAL COMPONENTS CONNECTED TO THE MECHANICAL SYSTEM.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM.

FBC(2014) 110.2

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15080032 CASE ADDR: 1800 SE 7 ST PAPAY, TERRY L

SCHULTZ, FRANCIS III

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. SIGNIFICANT REDECKING OF DOCK STRUCTURE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15070227 CASE ADDR: 1032 NE 8 AV ACOMB, JACK OWNER:

ACOMB, LAWRENCE T

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. WOOD FENCE WITH NO PERMIT.

2. CONSTRUCTION OF AN ENCLOSURE WITH NO PERMIT.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15070731
CASE ADDR: 1119 NW 10 PL
OWNER: ADAMS MEM LLC
INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. CONVERTED FROM 2/1 INTO A 3/2.
- 2. CONVERTED UTILITY ROOM INTO A BATHROOM.

FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. INSTALLED A SPLIT AC SYSTEM.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS. INSTALLATION AND MODIFICATION BUT NOT LIMITED TO:

1. INSTALLED FIXTURES IN CONVERTED BATHROOM. INSTALLED WATER HEATER.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM. THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ALTERED ELECTRICAL SYSTEM AND THERE ILLEGAL ELECTRICAL CONNECTIONS UNDER THE KITCHEN SINK. WATER HEATER THAT WHEN IN USE THE BREAKERS GET VERY HOT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

._____

CASE NO: CE15070738

CASE ADDR: 1301 NE 2 AV

OWNER: SETTON, JOHN

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. RE-ROOFING WITH NO PERMIT.

FBC(2014) 105.3.1.4.10 REQUIREMENTS FOR ROOF PERMIT.

FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED WINDOWS WITHOUT PERMIT.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVER-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPT, THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15070786

CASE ADDR: 1437 NE 56 ST

OWNER: BRODETZKI, YUVAL

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.1

THE BUILDING HAS BEEN ALTERED WITHOUT A PERMIT. IT HAS BEEN CONVERTED TO FIVE UNITS. APPROVED USE IS FOR A SINGLE UNIT FAMILY RESIDENCE.

FBC(2014) 105.3.1.4.4

THE PLUMBING HAS BEEN ALTERED WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM HAS BEEN ALTERED WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.15

WINDOW AND DOOR INSTALLATIONS AND ALTERATIONS WITHOUT A PERMIT

FBC(2014) 105.4.1.2

OWNER OF RECORD IS RESPONSIBLE TO ABIDE BY FLORIDA BUILDING CODE AS OUTLINED IN FLORIDA STATUTES.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 111.4.1

PROPERTY IS A SINGLE FAMILY RESIDENCE APPROVED FOR SINGLE USE. THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A SINGLE FAMILY TO A FIVEPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE15082171 CASE ADDR: 2841 SW 9 ST

OWNER: VERNEUS, ALPHONSINE H/E

GASTON, IBRAM

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. DEN CONVERTED TO AN EFFICIENCY APARTMENT WITH A BATHROOM.

FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BUILT A BATHROOM IN THE DEN WITHOUT ACQUIRING THE REQUIRED PERMITS.

FBC(2014) 105.3.1.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ALTERED THE ELECTRICAL SYSTEM IN THE COVERTED DEN TO EFFICIENCY WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINNING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. INSTALLED A CENTRAL A/C CONDENSOR UNIT WITHOUT THE REQUIRED PERMIT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

FBC (2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A DUPLEX TO A FOURPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

1. CONVERTED DEN TO AN EFFICIENCY.

FBC(2014) 116.2.1.2.5

THIS BUILDING IN ITS PRESENT CONDITION DOES NOT MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR MINIMUM MAINTENANCE STANDARD AND THE FORT LAUDERDALE MINIMUM HOUSING CODE. IT MUST BE REPAIRED BY THE OWNERS OR DEMOLISHED:

FIRE DAMAGE IN THE BUILDING IS A POTENTIAL LIFE AND SAFETY HAZARD SINCE THE BUILDING IS STILL ENERGIZED AND OCCUPIED.

CASE NO: CE15070923 CASE ADDR: 216 ROSE DR

OWNER: CECERE, LEONARD & MARY M

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED CANOPY AND ANCHORED TO BUILDING WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ENCLOSED CARPORT AND CONVERTED INTO GARAGE WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED WINDOWS AT CARPORT ALTERATION WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.17

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED GARAGE DOOR TO CONVERTED CARPORT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

._____

CASE NO: CE15080366 CASE ADDR: 6980 NW 29 WY

OWNER: SFS INVESTMENTS LLC

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. STUCCO AND FASCIA BOARDS REPLACED WITHOUT A

PERMIT.

FBC(2014) 105.3.1.4.10

ROOF REPAIRED WITHOUT A PERMIT

FBC(2014) 105.3.1.4.18

FENCE AND GATES REPAIRED WITHOUT A PERMIT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15081297
CASE ADDR: 3051 NW 23 ST
OWNER: WILLIAMS, THERESA

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. BUILT AN ADDITION WITHOUT A PERMIT WHICH IS DEEMED UNSAFE AND IS STRUCTURALLY FAILING.

FBC(2014) 105.3.1.4.5

ELECTRICAL SYSTEM ALTERED TO INCORPORATE ILLEGAL ADDITION WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2014) 105.3.1.4.11

AIR CONDITIONING INSTALLED AND ALTERED TO INCORPORATE ILLEGAL ADDITION WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2014) 105.3.1.4.15 INSTALLATION OF DOOR WITHOUT OBTAINING THE REOUIRED PERMITS.

FBC(2014) 105.3.1.5

DESIGN AND ENGINEERING DOCUMENTS NOT SUBMITTED TO OBTAIN PERMIT APPROVAL.

FBC (2014) 116.1.1

THIS BUILDING IN ITS PRESENT CONDITION DOES NOT MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR MINIMUM MAINTENANCE STANDARD AND THE FORT LAUDERDALE MINIMUM HOUSING CODE AND IT MUST BE REPAIRED BY THE OWNERS OR DEMOLISHED:

1. STRUCTURE BUILT AT EDGE OF POOL WITHIN THE REQUIRED 5 FOOT SETBACK WITHOUT OBTAINING THE REQUIRED PERMITS. POOL NOT DESIGNED TO SUPPORT THE WEIGHT OF THE ILLEGAL STRUCTURE.

FBC(2014) 116.2.1.2.4

THIS BUILDING IN ITS PRESENT CONDITION DOES NOT MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR MINIMUM MAINTENANCE STANDARD AND THE FORT LAUDERDALE MINIMUM HOUSING CODE. IT MUST BE REPAIRED BY THE OWNERS OR DEMOLISHED:

1. THE ROOF IS SAGGING AND HAS THE POTENTIAL FOR FAILURE.

CASE NO: CE15080572 CASE ADDR: 1201 NE 5 AV

OWNER: EM INVESTMENT REV TR

MILITZOK & LEV PA TRSTEE

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. ADDED A FIFTH UNIT TO A FOURPLEX, ALTERED THE CONFIGURATION OF THE WALLS, THE ELECTRICAL, MECHANICAL AND PLUMBING.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

FBC(2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A FOUR UNITS TO FIVE UNITS WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

FBC(2014) 111.4.1

UNIT OCCUPIED IN VIOLATION OF THIS CODE MUST BE VACATED.

CASE NO: CE15071515 CASE ADDR: 1135 NW 7 AV

OWNER: TIITF/HRS-YOUTH SERV

BROWARD CHILDREN'S SHELTER

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2014) 1003.6

WINDOWS AND DOORS HAVE BEEN BLOCKED LIMITING EGRESS AS REQUIRED BY CODE.

FBC(2014) 1006.1

EMERGENCY EXIT LIGHTS MUST BE MADE FUNCTIONAL AS REQUIRED BY CODE.

FBC(2014) 1006.3

EMERGENCY EXIT LIGHTS MUST BE MADE FUNCTIONAL AS REQUIRED BY CODE.

FBC(2014) 1008.1.9.1

ALL DOORS MUST HAVE LATCHES AND HANDLES AS TO BE ABLE TO BE OPENED FROM THE INTERIOR OF THE FLOOR AREA THEY SERVICE AS REQUIRED BY CODE.

FBC(2014) 1008.1.9.3 4.

DOUBLE KEYED DEAD BOLTS MUST BE REMOVED AS THEY PREVENT EGRESS FROM THE FLOOR AREA THEY SERVE AS REQUIRED BY CODE.

FBC(2014) 1029.1

ALL ROOMS THAT ARE DESIGNED WITH WINDOWS THAT CAN SERVE AS A MEANS OF EGRESS MUST HAVE AT MINIMUM ONE WINDOW UNBLOCKED AS TO SERVE AS THE SECONDARY MEANS OF EGRESS AS REQUIRED BY CODE.

FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

1. ALL WORK AND CORRECTIONS REQUIRING PERMITTING MUST COMPLY WITH THIS SECTION OF THE CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

FBC(2014) 1522.3.4

NO WIRE SHALL BE WITHIN THE PHYSICAL LIMITS IDENTIFIED BY THE SECTION OF THIS CODE.

NEC 110.26

WORKING SPACE AROUND PANELS MUST MEET THIS SECTION OF THE CODE.

NEC(2005) 110.12

ALL UNUSED OPENING IN ELECTRICAL PANELS MUST BE SEALED.

NEC(2005) 110.22

ALL PANELS AND MEANS OF DISCONNECT MUST BE IDENTIFIED AND LABELED IDENTIFYING THE CIRCUITS THEY SERVE.

NEC(2005) 110.27

ALL ENERGIZED CONNECTIONS MUST BE GUARDED FROM UNAUTHORIZED CONTACT.

NEC(2005) 210.8

AREAS REQUIRING GFI PROTECTION ON THE EXTERIOR AND WET KITCHEN AND BATHROOM AREA MUST BE MADE OPERABLE.

NEC(2005) 230.24

PANEL CANNOT BE BLOCKED AND MUST BE MADE ACCESSIBLE FOR EMERGENCY DISCONNECT IF REQUIRED.

NEC(2005) 406.11

DWELLING UNITS MUST HAVE TAMPER-RESISTANT RECEPTACLES.

NEC(2005) 408.38

ALL PANELS DISCONNECT BOXES MUST BE SECURED AS TO NOT HAVE ACCESS TO ENERGIZED CONNECTIONS OR HAVE A DEAD FRONT COVER.

NEC (2005) 408.4

ALL PANELS AND MEANS OF DISCONNECT MUST BE IDENTIFIED AND LABELED IDENTIFYING THE CIRCUITS THEY SERVE.

NEC (2005) 440.22 (A)

CIRCUIT/FUSE/BREAKER MUST BE COMPATIBLE AND BE ABLE TO CARRY THE LOAD OF THE MECHANICAL EQUIPMENT THEY SERVE.

NEC(2005) 440.22(C)
CIRCUITS MUST MEET MANUFACTURERS CRITERIA.

CASE NO: CE14061177 CASE ADDR: 3505 SW 12 CT

OWNER: MCFARLANE, CHRISTINE INSPECTOR: ALEJANDRO DELRIO

INSPECTOR. ALEGANDRO DELICTO

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS, INSPECTIONS AND THE CERTIFICATE OF OCCUPANCY:

- 1. THE GARAGE OR CARPORT WAS ENCLOSED INTO LIVING SPACE WITHOUT A C.O.
- 2. THE WINDOWS IN THE DWELLINGS' OPENINGS WERE REPLACED.
- 3. THE KITCHEN AND BATHROOM WERE UPGRADED WITH NEW PLUMBING AND ELECTRICAL FIXTURES.
- 4. NEW CABINETRY WAS INSTALLED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14061439
CASE ADDR: 2630 NE 18 ST
OWNER: LOONEY, DANNY

HERRERA, SOFIA GINA

INSPECTOR: ALEJANDRO DELRIO

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:
1. CARPORT CONSTRUCTION.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITING PROCESS.

CASE NO: CE14120581
CASE ADDR: 3001 SE 5 ST

OWNER: SOPHIA ENTERPRISES INC

INSPECTOR: ALEJANDRO DELRIO

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:
1. NEW PLUMBING FIXTURES IN SECOND FLOOR

RESTROOMS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15030646
CASE ADDR: 508 NW 15 AV
OWNER: CHIWARA, GRACE
INSPECTOR: ALEJANDRO DELRIO

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

1. THE WINDOWS ARE BEING REPLACED IN THE DWELLING

OPENINGS WITHOUT THE REQUIRED PERMIT.

A STOP WORK WAS ISSUED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15042036

CASE ADDR: 3209 NE 36 ST # 4B
OWNER: MIGA, PATRICIA ANN T &

MIGA, STEVEN J

INSPECTOR: ALEJANDRO DELRIO

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANER:

1. REAR PATIO ENCLOSURE INSTALLED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITING PROCESS.

CASE NO: CE15050511 CASE ADDR: 1132 NW 5 CT

MCCULLOUGH, JOHNNY

HALL, ODESSA

INSPECTOR: ALEJANDRO DELRIO

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS.

1. THIS SINGLE STORY DUPLEX HAS BEEN CONVERTED

INTO A FOURPLEX.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REOUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS

BEEN CHANGED FROM THE ORIGINALLY PERMITTED

OCCUPANCY CLASSIFICATION OF A DUPLEX TO A FOURPLEX

WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CE15051584 CASE NO: CASE ADDR: 1621 NE 20 AV OWNER: PIEKARSKI, JASON INSPECTOR: ALEJANDRO DELRIO

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS.

- 1. THERE IS A CURRENT PERMIT# 15042829, FOR DOOR AND WINDOW REPLACEMENTS. IT APPEARS THAT THEY ARE WORKING BEYOND THE SCOPE OF THE ISSUED PERMIT AS THE BATHROOM AND KITCHEN HAVE RENOVATIONS IN PROGRESS.
- 2. WATER HEATER HAS BEEN REMOVED FROM ITS APPROVED LOCATION.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED

AND/OR COVERED-UP WITHOUT THE REQUIRED

INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15051950
CASE ADDR: 6520 NE 21 AV
OWNER: PETERS, WILLIAM A

DAVIDSON, WARREN

INSPECTOR: ALEJANDRO DELRIO

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. REPLACEMENT OF AIR CONDITIONING UNIT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPT, THROUGHOUT THE

PERMITING PROCESS.

CASE NO: CE15061198
CASE ADDR: 1616 SE 2 CT
OWNER: FINN, ZACHARY
INSPECTOR: ALEJANDRO DELRIO

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. PAVERS INSTALLED ON DRIVEWAY AND SWALE AREA.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITING PROCESS.

CASE NO: CE15062080 CASE ADDR: 4881 NW 9 TER OWNER: CHARLES, ANNEMISE INSPECTOR: ALEJANDRO DELRIO

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. WINDOW OPENING WAS ENCLOSED. 2. CENTRAL A/C UNIT WAS REPLACED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REOUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITING PROCESS.

CASE NO: CE14060528 CASE ADDR: 1213 NW 3 ST

TOTAL HOUSING INC OWNER:

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS AND THE REQUIRED C.O. FROM THE CITY OF FORT LAUDERDALE.

- 1. THE CARPORT HAS BEEN ENCLOSED AND A BATHROOM WAS ADDED TO IT.
- 2. THE DWELLING HAS BEEN CONVERTED FROM A SINGLE FAMILY TO MULTI-FAMILY OR DUPLEX.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A SINGLE FAMILY TO A MULTI-FAMILY DWELLING WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY

FROM THE BUILDING DEPARTMENT.

CASE NO: CE14072166
CASE ADDR: 907 NW 12 TER
OWNER: HASAN, ABEER
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS AS FOLLOW:

- 1. THE OUTSIDE WALLS WERE RE-STUCCOED.
- 2. ELECTRICAL WIRES ARE EXPOSED IN THE METER CAN.
- 3. THE BATHROOM WINDOW AND THE EXTERIOR DOOR WERE REPLACED.
- 4. INTERIOR ALTERATIONS ARE IN PROGRESS: DRYWALL, PLUMBING AND ELECTRICAL FIXTURES HAVE BEEN REPLACED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15020101
CASE ADDR: 1616 NW 16 ST
OWNER: RHA 2 LLC
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

- 1. THE WINDOWS HAVE BEEN REPLACED ON THE DWELLING
- 2. THE INTERIOR OF THE PROPERTY IS BEING GUTTED.
 ALTERATIONS TO THE EXISTING AND APPROVED FLOOR
 PLAN ARE ON THE WAY WITH THE REMOVAL OF
 PARTITIONS, ELECTRICAL AND PLUMBING IN THE WALLS.
 THEY ARE IN THE PROCESS OF BUILDING A NEW FLOOR
 LAYOUT OF THE DWELLING.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15041350
CASE ADDR: 1162 NW 9 TER

OWNER: MERSAN HOLDINGS LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

1. STRUCTURAL, PLUMBING AND ELECTRICAL ALTERATIONS ARE BEING DONE TO THE BUILDING. ALL THE WINDOWS

AND DOORS WERE REPLACED IN THE OPENINGS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITING AND INSPECTION PROCESS.

CASE NO: CE14070534

CASE ADDR: 200 S BIRCH RD # 814
OWNER: SCHILLIZZI, LANCE
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH AN INTERIOR RENOVATION WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

FBC(2010) 110.9

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW

AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.
SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND
PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS

CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE14040754
CASE ADDR: 91 COMPASS LA

OWNER: BRESLOW, JULIAN MARIE

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 116.2.1.2.1

PART OF THE SEAWALL HAS BEEN DAMAGED AND NEEDS TO

BE REPAIRED.

CASE NO: CE14111609

CASE ADDR: 545 S FTL BEACH BLVD 1101

OWNER: WISMER, GERALD BRUCE
NEW OWNER: BRENNAN, MICHAEL
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INTERIOR REMODELING WITHOUT THE REQUIRED STRUCTURAL PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.3

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INTERIOR DEMOLITION OF THE FRAMING AND DRYWALL THROUGHOUT THE KITCHEN, BATHROOMS, AND OTHER AREAS OF THIS UNIT WITHOUT THE REQUIRED DEMOLITION PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THIS CONDO UNIT HAS BEEN ALTERED WITH THE REMOVAL OF THE PLUMBING FIXTURES IN THE KITCHEN AND BATHROOMS WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH THE ALTERATION OF ELECTRICAL WIRING AND DEVICES WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THIS CODE CASE WILL REQUIRE THAT ALL REQUIRED PERMITS ARE OBTAINED, INSPECTED, PASSED AND CLOSED IN ORDER TO COMPLY AND CLOSE THIS CODE CASE IN THIS CONDO BUILDING.

.....

CASE NO: CE15020109

CASE ADDR: 2100 S OCEAN LA # 502

OWNER: PANE, BRIAN D INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH INTERIOR ALTERATIONS THAT COMPROMISED THE PARTY/FIRE WALL BETWEEN THE TWO UNITS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH INTERIOR ELECTRICAL ALTERATIONS WHERE ROMEX WIRING WAS INSTALLED. THIS WORK IS ILLEGAL IN A HI-RISE CONDO BUILDING AND DOES NOT MEET CODE. THIS WORK WAS DONE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.11

THIS CONDO UNIT HAS BEEN ALTERED WITH INTERIOR MECHANICAL ALTERATIONS WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15040200

CASE ADDR: 4100 GALT OCEAN DR # 610
OWNER: GUTIERREZ, MARIO & SILVANA

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH THE COMPLETE INTERIOR DEMOLITION AND RENOVATION WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.11

THIS CONDO UNIT HAS BEEN ALTERED WITH MECHANICAL WORK BEING PERFORMED WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THIS CONDO UNIT HAS BEEN ALTERED WITH PLUMBING WORK BEING PERFORMED WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH ELECTRICAL WORK BEING PERFORMED WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15041506 CASE ADDR: 928 NE 20 AVE

OWNER: NE 20 AVE PROPERTIES LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH A CANOPY AWNING INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED WITH A CANOPY AWNING INSTALLED THAT HAS ELECTRICAL INSTALLED THROUGHOUT WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15071130

CASE ADDR: 117 S GORDON RD
OWNER: LAURENT, REGINALD
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.3.1.4.1

THE DOCK AT THE REAR OF THE PROPERTY WAS

REFINISHED WITH AN APPLIED PERMIT# 15060297. TODAY

IT HAS BECOME WORK WITHOUT A PERMIT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15080187

CASE ADDR: 2933 POINSETTIA ST
OWNER: CORTEZ PROPERTY DEV LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 116.1.1

- 1. THERE ARE LIGHT FIXTURES MISSING IN THE WALKWAYS AND STAIRWELLS OF THIS BUILDING. THISIS A VIOLATION UNDER THE MINIMUM HOUSING CODE.
- 2. THERE ARE UNITS IN THIS BUILDING WHERE THE KITCHENS AND BATHROOMS HAVE BEEN PARTIALLY DEMOLISHED OR COMPLETELY DEMOLISHEDED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS. THIS IS ALSO A VIOLATION UNDER THE MINIMUM HOUSING CODE.
- 3. THE STAIRWELL ON THE NORTH END OF THE BUILDING LEADING TO THE ROOFTOP AREA HAS BEEN CLOSED OFF, FRAMED, SHEATHING AND STUCCOED OVER WITHOUT THE REQUIRED PERMITS AND/ OR INSPECTIONS.
- 4. THERE ARE RENTAL UNITS IN THIS BUILDING THAT HAVE HAD KITCHENS AND BATHROOMS REMODELED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.
- 5. THE LOW VOLTAGE ELECTRICAL BOX ON THE GROUND FLOOR IN THE GARAGE AREA IS IN DISREPAIR. WIRING IS EXPOSED AND HANGING LOOSE. THIS IS AN ELECTRICAL CODE VIOLATION AND A MAINTENANCE VIOLATION.
- 6. THERE ARE ILLEGAL FIRE DOORS THAT HAVE BEEN INSTALLED IN THE STAIRWELLS AND THE ENTRY DOORS OF THE UNITS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS. THIS IS ALSO A FIRE CODE VIOLATION.
- 7. THE ILLEGAL UNIT ON THE ROOF TOP HAS A PATIO AREA WHICH HAS NO BALCONY RAILING IN PLACE AND IS A FOUR STORY DROP. THIS IS A LIFE SAFETY ISSUE.

- 8. THERE ARE ELECTRICAL PANELS THAT HAVE NOT BEEN MAINTAINED AND ALSO HAVE MISSING BREAKERS. THIS IS AN ELECTRICAL CODE VIOLATION AND ALSO A POTENTIAL LIFE SAFETY ISSUE.
- 9. THERE ARE ELECTRICAL BOXES AND OUTLETS THAT ARE ROTTED OUT AND IN NEED OF REPLACEMENT. THIS IS AN ELECTRICAL CODE VIOLATION.
- 10. THERE ARE STAIRWELL DOORS WHICH THE DOOR CLOSERS DO NOT CLOSE THE DOOR PROPERLY AND THE DOORS THEMSELVES DO NOT CLOSE PROPERLY. THIS IS A MAINTENANCE AND FIRE CODE VIOLATION.

FBC(2014) 116.1.2

1. THERE IS AN ILLEGAL ROOF TOP ADDITION THAT IS CURRENTLY ADVISED AS A STUDIO RENTAL. THIS ILLEGAL ROOF TOP ADDITION WAS A CODE CASE FROM OCTOBER 22ND, 2002. PERMIT 03060376 WAS APPLIED FOR ON 06-05-2003, FAILED PLAN REVIEW. THE PERMIT WAS NEVER ISSUED AND THE APPLICATION WAS PURGED FROM OUR SYSTEM ON NOVEMBER 21, 2003.

FBC(2014) 116.2.1.1.2

1. THERE IS AN UNWARRANTED ACCUMULATION OF DEBRIS AND OTHER COMBUSTIBLE MATERIAL WHICH INCLUDES BUT IS NOT LIMITED TO: COUCHES, FUEL CONTAINERS, SCREEN DOORS, ABANDONED VEHICLES, PAINT CANS AND LUMBER. THIS IS A POTENTIAL FIRE HAZARD.

FBC(2014) 116.2.1.1.3

- 1. NFPA 1:13.6.9.3.1.1.1 OUT FE 05/14
 TO WIT: THE FIRE EXTINGUISHER(S) HAS/HAVE NOT BEEN SERVICED AND TAGGED BY A STATE LICENSED COMPANY WITHIN THE PAST 12 MONTHS.
 CORRECTIVE ACTION: HAVE THE FIRE EXTINGUISHER(S) SERVICED AND TAGGED BY A STATE LICENSED COMPANY.
- 2. NFPA 101:7.9.2.1 SERVICE ALL EMERGENCY LIGHTS. TO WIT: THE EMERGENCY LIGHT DOES NOT ILLUMINATE AS DESIGNED.

CORRECTIVE ACTION: REPAIR THE EMERGENCY LIGHT TO ILLUMINATE AS DESIGNED.

3. NFPA 101:7.10.5.2.1 SERVICE ALL EXIT SIGNS. TO WIT: THE EXIT SIGN DOES NOT ILLUMINATE AS DESIGNED.

CORRECTIVE ACTION: REPAIR THE EXIT SIGN TO ILLUMINATE AS DESIGNED.

4. NFPA 1:10.11.6 REMOVE ALL GRILLS FROM STRUCTURE.

TO WIT: A(AN) HIBACHI, GRILL, OR OTHER SIMILAR DEVICE(S) USED FOR COOKING, HEATING, OR ANY OTHER PURPOSE IS BEING USED OR KINDLED ON A BALCONY, UNDER A OVERHANGING PORTION, OR WITHIN 10 FT (3 M) OF A STRUCTURE.

CORRECTIVE ACTION: DISCONTINUE THE USE OF AND REMOVE THE HIBACHI, GRILL, OR OTHER SIMILAR DEVICES USED FOR COOKING, HEATING, OR ANY OTHER PURPOSE THAT IS BEING USED OR KINDLED ON A BALCONY, UNDER AN OVERHANGING PORTION, OR WITHIN 10 FT (3 M) OF THE STRUCTURE.

5. NFPA 1:1.7.6.2 FIX F/A REPAIR THE FIRE ALARM SYSTEM.

TO WIT: THE FIRE ALARM SYSTEM APPEARS TO HAVE NO POWER AND IS NOT FUNCTIONAL AT THIS TIME. NO ACCESS TO THE ELECTRIC METER ROOM TO VERIFY THIS CONDITION. PROVIDE ACCESS.

CORRECTIVE ACTION: REPAIR THE FIRE ALARM ASAP AND PROVIDE ACCESS TO THE ELECTRIC METER ROOM TO VERIFY THE CONDITION OF THE BUILDING FIRE ALARM SYSTEM.

6. NFPA 101:31.3.4.5.1 REPAIR ALL SMOKE DETECTORS.

TO WIT: HARDWIRED SMOKE DETECTORS ARE NOT BEING MAINTAINED IN ACCORDANCE WITH NFPA 101:31.3.4.5.1.

CORRECTIVE ACTION: INSTALL HARDWIRED SMOKE DETECTORS IN ACCORDANCE WITH NFPA 101:31.3.4.5.1. POWERED BY THE BUILDINGS ELECTRIC SYSTEM WITH BATTERY BACK?UP

- 7. NFPA 101:7.2.1.8.1 REPAIR ALL DOORS TO SELF? CLOSE AND LATCH.
- TO WIT: SELF CLOSING OR AUTOMATIC CLOSING DOOR(S) DON'T SELF CLOSE AND LATCH.

CORRECTIVE ACTION: REPAIR THE SELF?CLOSING OR AUTOMATIC?CLOSING DOOR(S) TO SELF?CLOSE AND LATCH.

8. NFPA 101:7.2.1.8.1 REPAIR ALL FIRE RATED STAIRWELL DOORS.

TO WIT: SELF CLOSING OR AUTOMATIC CLOSING DOOR(S) DON'T SELF CLOSE AND LATCH.

CORRECTIVE ACTION: REPAIR THE SELF CLOSING OR AUTOMATIC CLOSING DOOR(S) TO SELF CLOSE AND LATCH.

9. NFPA 1:11.1.2 REPAIR ALL EXPOSED WIRING.
TO WIT: ELECTRICAL WIRING NOT PER NFPA 70,
NATIONAL ELECTRICAL CODE.
CORRECTIVE ACTION: REPAIR ALL EXPOSED WIRING IN
ALL APARTMENTS AND ON THE EXTERIOR OF THE
STRUCTURE.
REPAIR WIRING TO BE CONSISTENT WITH NFPA 70,
NATIONAL
ELECTRICAL CODE.

10. NFPA 1:4.5.8.6 REPLACE / REPAIR ALL MISSING HAND RAILINGS.

TO WIT: SAFEGUARDS, RAILING ARE MISSING AND HAVE BEEN REMOVED FROM THE 4TH FLOOR AND ARE NOT SECURED IN AREAS OF THE 3RD AND 2ND FLOOR. CORRECTIVE ACTION: PERMITS SHALL BE OBTAINED TO SECURE AND INSTALL THE PROPER FALL PROTECTION.

11. 9999 UNSAFE BUILDING.

TO WIT: THE BUILDING OFFICIAL OF THE CITY OF FORT LAUDERDALE HAS POSTED THIS PROPERTY AS AN UNSAFE STRUCTURE TODAY (TUESDAY AUGUST 4th, 2015). CORRECTIVE ACTION: COMPLY WITH THE ORDER OF THE BUILDING OFFICIAL.

12. NFPA 1:11.1.10 REPLACE ALL MISSING ELECTRICAL COVERS. TO WIT: THERE IS/ARE MISSING ELECTRICAL COVER(S). CORRECTIVE ACTION: REPLACE ALL MISSING ELECTRICAL COVERS IN ALL APARTMENTS AND ELECTRICAL PANELS. REPLACE ALL MISSING ELECTRICAL COVERS.

FBC(2014) 116.2.1.2.1

- 1. THERE ARE BALCONY RAILINGS WHICH HAVE BROKEN
 FREE AND ARE NOW ATTACHED WITH ANGLE BRACKETS.
 THESE RAILINGS ARE LOOSE AND CAN EASILY BE BROKEN
 FREE CAUSING A FALL HAZARD AND IS A LIFE SAFETY ISSUE.
- 2. THERE ARE OVERHEAD LIGHT FIXTURES THAT HAVE BROKEN FREE AND ARE HANGING LOOSE AND ARE A POTENTIAL LIFE SAFETY ISSUE.

FBC(2014) 116.2.1.2.2

1. THERE ARE SEVERAL AREAS THROUGHOUT THE BUILDING WHERE THERE IS SIGNIFICATE DETERIORATION OF THE CONCRETE COLUMNS, CONCRETE BEAMS, AND CONCRETE WALKWAYS WHERE REBAR IS EXPOSED. THIS DETERIOATION HAS COMPROMISED THE STRUCTURAL INTEGRITY OF THIS BUILDING CAUSING POTENTIAL LIFE SAFETY ISSUES.

FBC(2014) 116.2.1.3.1

- 1. THERE IS AN ILLEGAL GAS LINE INSTALLED ON THE NORTH SIDE OF THE BUILDING. THIS ILLEGAL GAS LINE WAS INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS. THE GAS LINE IS BLOCKING TWO DOORS MAKING THEM UNABLE TO BE OPENED.
- 2. THERE ARE MULTIPLE UNITS THAT ARE IN THE PROCESS OF BEING REMODELED. THIS WORK INCLUDES BUT IS NOT LIMITED TO THE DEMOLITION OF KITCHENS AND BATHROOMS, PLUMBING, ELECTRICAL AND STRUCTURAL WORK BEING DONE. THIS WORK HAS COMMENCED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

CASE NO: CE15081970 CASE ADDR: 5300 NE 24 TER

OWNER: CROSS FOX CONDO ASSN INC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH A STRUCTURE BUILT IN THE POOL AREA WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULED AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15091319
CASE ADDR: 307 NE 23 AV

OWNER: WALTER A CROWELL TR

CROWELL, WALTER A TRSTEE

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. THE INSTALLATION OF AN OUTDOOR KITCHEN

STRUCTURE BUILT WITHOUT THE REQUIRED PERMIT AND/OR

INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE INSTALLATION OF A GAS LINE INSTALLED FOR AN OUTDOOR KITCHEN WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15091410

CASE ADDR: 736 N VICTORIA PARK RD

OWNER: MARTINON, MARIE

LAURENCE TERNINCK, JA

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH WORK PERFORMED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. DRIVEWAY HAS BEEN DEMOLISHED.
- 2. A CONCRETE PATIO AND WALKWAY HAVE BEEN POURED AT THE FRONT OF THE HOUSE.
- 3. WINDOWS WERE REPLACED.
- 4. THE KITCHEN AND INTERIOR WERE REMODELED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WITH PLUMBING WORK PERFORMED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE REMOVAL AND REPLACEMENT OF PLUMBING FIXTURES IN THE KITCHEN WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WITH ELECTRICAL WORK PERFORMED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE ELECTRICAL PANEL BEING REPLACED, THE KITCHEN BEING REMODELED TO INCLUDE REPLACING DEVICES AND OTHER INTERIOR ELECTRICAL WORK WITHOUT THE REQUIRED PERMITS AND OR INSPECTIONS.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

FBC (2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15091532

CASE ADDR: 1432 N ANDREWS AV

OWNER: RHA 2 LLC INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH INTERIOR AND EXTERIOR REMODELING WORK WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15092005

CASE ADDR: 1800 N ANDREWS AVE # 05K

OWNER: LUTHY, HEDY

A & H LUTHY REV LIV TR ETAL

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES

BUT IS NOT LIMITED:

1. THE COMPLETE DEMOLITION OF THE KITCHEN AND BATHROOM WITHOUT THE REQUIRED STRUCTURAL PERMIT AND OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAS HAD PLUMBING ALTERATIONS PERFORMED WHICH INCLUDE BUT IS NOT LIMITED TO:

1. REMOVAL OF PLUMBING FIXTURES IN THE KITCHEN AND BATHROOM WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS HAD ELECTRICAL ALTERATIONS PERFORMED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE REMOVAL OF THE CIRCUITS IN THE ELECTRICAL PANEL AND THE REMOVAL OF ALL THE ELECTRICAL DEVICES THROUGHOUT THIS CONDO UNIT WITHOUT THE REQUIRED PERMITS AND OR INSPECTIONS.

FBC(2014) 109.3.3

THE CONDO UNIT WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15100625

CASE ADDR: 2420 SE 17 ST # 305-C OWNER: JMB 2420 INVESTMENTS LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC (2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO THE KITCHEN AND BATHROOM BEING COMPLETELY REMODELED TO INCLUDE:

1. DEMOLITION OF KITCHEN WALL, FRAMING, TILE BACKING BOARD ALL WORK COMPLETED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE PLUMBING FIXTURES BEING REMOVED AND REPLACED IN THE KITCHEN AND BATHROOM AND THE INSTALLATION OF A TANKLESS WATER HEATER WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL HI-HAT LIGHTING INSTALLED. THE ELECTRICAL DEVICES IN THE KITCHEN AND BATHROOM BEING REPLACED AND THE INSTALLATION OF AN ELECTRICAL TANKLESS WATER HEATER WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

THIS CODE CASE WILL REQUIRE ARCHITECTURAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL TO ADDRESS THE VIOLATIONS AND THE NEEDED CORRECTIONS THAT NEED TO BE MADE FOR THIS CONDO UNIT.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15100769

CASE ADDR: 1700 SE 15 ST # PH401

OWNER: FALLA, JUSTIN B INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. THE KITCHEN WAS COMPLETELY DEMOLISHED.
- 2. THE TWO BATHROOMS WERE COMPLETELY DEMOLISHED.
- 3. INTERIOR WALLS BEING REMOVED AND DRYWALL INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAD BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE REMOVAL OF THE PLUMBING FIXTURES IN THE KITCHEN AND BATHROOMS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE REMOVAL OF THE ELECTRICAL DEVICES IN THE KITCHEN, BATHROOMS AND OTHER WALL AREAS WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC (2014) 107.1.1

THE CONDO UNIT OWNER WILL BE REQUIRED TO SUBMIT ARCHITECTURAL DRAWINGS TO ADDRESS ALL OF THE RENOVATION WORK BEING DONE IN THIS UNIT. A COMPLETE DEMOLITION DRAWING/PAGE WILL NEED TO BE INCLUDED AND ADDRESS THE INTERIOR WALLS THAT HAVE BEEN REMOVED AND THE FUTURE LAYOUT OF THE PROPOSED RENOVATION.

FBC(2014) 110.6

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE ATF PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15101783

CASE ADDR: 1180 SEABREEZE BLVD

OWNER: SOUTHEAST HOSPITALITY CORP

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. CONCRETE RESTORATION WORK BEING PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS ELECTRICAL VIOLATION WHICH INCLUDE BUT ARE NOT LIMITED TO:

1. VIOLATIONS THAT NEED TO BE CORRECTED AND WORK PERFORMED BY A LICENSED ELECTRICIAN WITH THE REOUIRED ELECTRICAL PERMIT AND INSPECTIONS.

FBC(2014) 107.1.1

THIS PROPERTY AND THE CONCRETE RESTORATION WORK THAT IS BEING PERFORMED WILL REQUIRE ARCHITECTURAL PLANS PREPARED BY A DESIGN PROFESSIONAL THAT WILL OUTLINE THE SCOPE OF WORK AND THE NEEDED REPAIRS THAT NEED TO BE MADE. THE WORK WILL REQUIRE PERMITS OBTAINED BY A GENERAL CONTRACTOR AND A STRUCTURAL ENGINEER WILL NEED TO BE THE SPECIAL INSPECTOR OF RECORD AND RECORDED THROUGH THE PERMITTING PROCESS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE ATF PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE13080252

CASE ADDR: 2500 E COMMERCIAL BLVD

OWNER: ALTO PROPERTY MANAGEMENT LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. INTERIOR RENOVATIONS.

FBC(2010) 105.4.4

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING FIXTURES INSTALLED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL WIRING AND DEVICES INSTALLED WITHOUT THE REQUIRED ELECTRICAL PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.11

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE MECHANICAL SYSTEM IS BEING ALTERED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15102509

CASE ADDR: 2500 E COMMERCIAL BLVD

OWNER: ALTO PROPERTY MANAGEMENT LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THIS COMMERCIAL OFFICE SPACE AND THE ADJOINING UNITS, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED AND BROUGHT INTO COMPLIANCE PER FLORIDA BUILDING CODE.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 105.1

THIS COMMERCIAL SPACE HAS BEEN COMPLETELY REMODELED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. FRAMING AND DRYWALL INSTALLED WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING FIXTURES INSTALLED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL WIRING AND DEVICES INSTALLED WITHOUT THE REQUIRED ELECTRICAL PERMITS AND/OR INSPECTIONS.

CASE NO: CE15102548

CASE ADDR: 200 S BIRCH RD # 209

OWNER: FEDERAL NATIONAL MORTGAGE ASSN

INSPECTOR: ROBERT MASULA

VIOLATIONS: 9-280(B)

THERE ARE BUILDING PARTS WHICH ARE DETERIORATED AND NOT MAINTAINED.

1. THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

A. THE ORIGINAL A/C WALL UNIT APPLIANCE HAS BEEN REMOVED ALONG WITH THE ORIGINAL APPLIANCE SHELVES THAT WAS ORIGINALLY ANCHORED INTO THE WALL OPENING. THE OPENINGS EITHER NEED TO BE PROPERLY CLOSED IN WITH A STRUCTURAL PERMIT SPECIFYING THE METHOD OF CONSTRUCTION TO BE USED. IF THE INTENTION IS TO REPLACE THESE A/C WALL APPLIANCE UNITS THEN A COMPLETE UNIT WITH THE STRUCTURAL ATTACHED SHELVES NEEDS TO BE PROPERLY INSTALLED AND ANCHORED INTO THE WALL OPENING. THIS WILL AT A MINIMUM REQUIRE A MECHANICAL PERMIT FOR REPLACING THE ENTIRE ASSEMBLY.

FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE PLUMBING BEING ALTERED IN THE BATHROOM BY REMOVING AND REPLACING THE TOILET AND SINK WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTION.

FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE ELECTRICAL PANEL BEING REMOVED AND REPLACED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 110.6

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

MASSEY HEARING SCHEDULED

CASE NO: CE08070448 CASE ADDR: 1431 NW 11 PL

OWNER: DRAGOSLAVIC, GORAN

DRAGOSLAVIC, TERESA

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE PROPERTY SUSTAINED MAJOR DAMAGE TO THE STRUCTURE AND THE INTERIOR CAUSED BY A FIRE BACK

ON JULY 7, 2008.

A STOP WORK ORDER WAS ISSUED ON JULY 11, 2011 FOR WORK IN PROGRESS. ALL THE REPAIRS WERE PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND

INSPECTIONS:

- 1. THE ELECTRICAL SYSTEM WAS DAMAGED AND IT HAS BEEN REPAIRED.
- 2. THE FAMILY ROOM CEILING RAFTERS WITH THE ROOF DECK WERE COMPLETELY BURNED AWAY. THEY HAVE BEEN REPLACED.
- 3. COMPLETE INTERIOR RESTORATION: ALL THE ELECTRICAL AND PLUMBING FIXTURES, THE DRYWALL ON THE CEILING AND WALLS, WITH ALL THE CABINETRY WERE REPLACED.
- 4. THE AIR CONDITIONING SYSTEM HAS BEEN REPLACED IN WHOLE OR IN PART FROM THE FIRE DAMAGE.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

CASE NO: CE11061307 CASE ADDR: 2021 NE 59 ST

OWNER: LANE, CHRISTOPHER E & WENDY B

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

1. THE GARAGE HAS BEEN ENCLOSED AND HAS BEEN

- THE GARAGE HAS BEEN ENCLOSED AND HAS BEEN CONVERTED TO LIVING SPACE.
- 2. THE GARAGE HAS BEEN ENCLOSED.
- 3. WINDOWS HAVE BEEN INSTALLED.
- 4. INTERIOR FRAMING AND DRYWALL HAVE BEEN INSTALLED.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. THE ENCLOSED GARAGE HAS BEEN AIR CONDITIONED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. PIPING AND FIXTURES HAVE BEEN INSTALLED DURING THE GARAGE ENCLOSURE.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. CIRCUITS HAVE BEEN ADDED/ALTERED DURING THE GARAGE ENCLOSURE.

FBC(2007) 109.10

WORK WAS PERFORMED AND/OR COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE ENCLOSED GARAGE OPENING, THE WINDOWS INSTALLED, AND THE AC UNIT, IF INSTALLED, HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE13101928
CASE ADDR: 2201 NW 23 LN
OWNER: MCGILL, SHERRI
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

THIS COMPLAINT CAME FROM FLFD. THIS SINGLE FAMILY DWELLING WAS DAMAGED BY A FIRE AS REPORTED TO US BY THE FIRE MARSHALL'S OFFICE.

- 1. FRAMING AND DRYWALL WORK WAS DONE TO REPAIR THE DAMAGED INTERIOR OF THE DWELLING.
- 2. WINDOWS WERE REPLACED. THE OUTSIDE WALL WAS REPAIRED AROUND THE OPENINGS.
- 3. THE DAMAGED ROOF DECK WAS REPAIRED OR REROOFED.
- 4. A DUCTED CENTRAL A/C WAS INSTALLED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14121727

CASE ADDR: 650 TENNIS CLUB DR # 110

OWNER: TOLSON, JOHN

TOLSON, LORI

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS FROM THE CITY.

STOP WORK ORDER ISSUED

1. FRAMING AND NEW DRYWALL WORK WITH ELECTRICAL AND PLUMBING RESTORATIONS ARE IN PROGRESS WITH NEW FIXTURES BEING INSTALLED INSIDE THE KITCHEN AND BATHROOMS AREAS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT OBTAINING THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15041750
CASE ADDR: 2456 NE 27 TER
OWNER: BILLITIER, DAVID
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.4.8

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

1. AN AWNING WAS ERECTED IN FRONT OF THE GARAGE AND SEVERAL AWNINGS WERE PLACED ABOVE THE OPENING OF THE DWELLING.

FBC (2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15090051 CASE ADDR: 1216 NE 2 ST

OWNER: MAUS, ARTHUR J & KAREN N

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.3.2.1

THE FOLLOWING PERMITS WERE LEFT TO EXPIRE AND THE POOL CONSTRUCTION WAS FINISHED. TODAY IT REMAINS

WORK WITHOUT PERMITS. IT IS A LIFE SAFETY VIOLATION DUE TO THE FACT THAT THE ELECTRICAL SYSTEM HAS NOTT BEEN FINALED AND THE CHILD

BARRIERS HAVE NOT BEEN APPROVED TO COMPLY WITH THE

FLORIDA CHILD PROTECTION ACT FS515.

1. ELECTRICAL PERMIT # 00070898 (WIRE IN PUMP

MOTOR, POOL LIGHT, GROUNDING).

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE13121229

CASE ADDR: 2655 FLAMINGO LN

OWNER: BARNABY, ROBERT J JR & CYNTHIA V

INSPECTOR: ALEJANDRO DELRIO

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

1. THE EXISTING DOCK ON THE WEST SIDE OF THE

PROPERTY WAS REPLACED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15011521 CASE ADDR: 1024 NW 12 ST

OWNER: RHA 2 LLC

INSPECTOR: ALEJANDRO DELRIO

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. WINDOWS AND DOORS WERE REPLACED AT THE

DWELLING.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITING PROCESS.

CASE NO: CE15040774
CASE ADDR: 208 SW 2 ST
OWNER: OLIVA OLIVA LLC

A I R ENTERPRISES LLC

INSPECTOR: ALEJANDRO DELRIO

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

1. STRUCTURAL, PLUMBING AND ELECTRICAL ALTERATIONS WERE DONE TO BUILD A WOOD SHED TO HOUSE THE ICEMAKER AND A COOLING SYSTEM THAT WAS INSTALLED AT THE FRONT OF THE STORE. BOTH WITHOUT THE APPROVAL OF THE BUILDING AND FIRE DEPARTMENTS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CE15060134 CASE NO: CASE ADDR: 2601 SW 13 PL HSBC BANK USA NA OWNER:

%OCWEN LOAN SERVICING

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS FOR WORK IN PROGRESS:

- 1. INSTALLING WOOD FENCE.
- 2. REBUILDING FRONT WITH PORCH (ROOF) OVERHANG.
- 3. WOOD SIDING WORK AT THE REAR OF THE DWELLING AND STRUCTURAL WORK AROUND THE WINDOWS.
- 4. THIS DWELLING WAS DAMAGED BY A FIRE ON SEPTEMBER 30, 2002 AS PER CASE CE02100033. THERE ARE NO PERMITS ON RECORD TO PERFORM AND RESTORE WORK AFTER THE FIRE.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT OBTAINING THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CE15061969 CASE NO: CASE ADDR: 1613 NW 14 ST

OWNER: SWAY 2014-1 BORROWER LLC

INSPECTOR: JOSE ABIN

PRESENTED BY INSPECTOR GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

- 1. INSTALLED CENTRAL AIR CONDITIONER.
- 2. ELECTRICAL WORK FOR CENTRAL A/C DISCONNECT.
- 3. INSTALLED WATER HEATER.
- 4. INTERIOR REMODELING.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE13091177
CASE ADDR: 3210 NW 63 ST

OWNER: STYCZYNSKY, RANDALL W

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

1. REPLACING WINDOWS AND DOORS.

2. ALTERING OPENING FROM WINDOWS TO DOORS, WHICH INCLUDES FILLED CELLS AND ELECTRICAL WORK.

ALL WORK DONE WITHOUT THE REQUIRED PERMITS OR INSPECTIONS.

FBC(2010) 105.4.15

REPLACING WINDOWS AND DOORS WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

FBC(2010) 105.4.5

ADDING ELECTRICAL WIRING, ELECTRICAL BOXES, AND FUTURE FIXTURES WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

FBC(2010) 1604.1

ALTERING EXTERIOR OPENINGS FOR BOTH WINDOWS AND DOORS THAT INCLUDES FILLED CELLS, BLOCK, POURED SILLS WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

CASE NO: CE14060058

CASE ADDR: 2500 LUCILLE DR

OWNER: KLAIRMONT, LARRY

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THERE ARE SEVERAL ITEMS THAT HAVE BEEN INSTALLED ON THIS PROPERTY WITHOUT FIRST OBTAINING THE

REQUIRED PERMITS TO INCLUDE:

A SMALL SHED.
 A GENERATOR.
 AN AWNING.
 A POOL HEATER.

CASE NO: CE14091251
CASE ADDR: 1736 SE 14 ST
OWNER: VERDUGO, CARLOS E
INSPECTOR: ROBERT MASULA

VIOLATIONS: 9-280(B)

- 1. THERE ARE BUILDING PARTS WHICH ARE DETERIORATED AND NOT MAINTAINED.
- 2. THE SEAWALL AT THIS PROPERTY IS IN NEED OF REPAIRS AND MAINTENANCE.

FBC(2010) 105.4.18

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF A FENCE WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.3

- 1. THIS PROPERTY HAS BEEN ALTERED WITH THE PARTIAL DEMOLITION OF A DOCK WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.
- 2. THE WOODEN DOCK HAS NOT BEEN MAINTAINED AND HAS NOW DETERIORATED FROM THE ELEMENTS. THIS STRUCTURE HAS NOW BECOME A WINDSTORM HAZARD AND IS UNSAFE.

CASE NO: CE15011800

CASE ADDR: 229 S FTL BEACH BLVD OWNER: EL-AD FL BEACH CR LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF AN AWNING DISPLAYING SIGNAGE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.8

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF AN ALUMINUM AWNING STRUCTURE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.
